


INDEX


	Page
DIMENSIONS	2
BRIEF SPECIFICATION	3
GENERAL LAYOUT OF LATHE	4
FOUNDATION PLANE	5
INSTALLATION	
LIFTING	6
CLEANING	6
INSTALLING	7
LUBRICATION CHECKS	8
CHUCKS AND CHUCK MOUNTING	9
OPERATION	
LATHE CONTROLS	11
ELECTRICAL CONTROLS	12
SPEED CONTROLS	14
THREADS AND FEEDS	16
THREADING DIAL INDICATOR	18
APRON CONTROLS	19
CROSS-SLIDE AND TOP SLIDE	20
TAIL STOCK	21
SERVICING & MAINTENANCE	
LATHE ALIGNMENT	22
END GEAR TRAIN	24
DRIVING BELTS	24
SLIDE WAYS ATTENTION	25
CROSS-SLIDE NUT	25
LUBRICATION	26
LUBRICATION DIAGRAM	28
WIRNING DIAGRAM	29
PARTS LIST	
ASSEMBLY	35
PART NUMBER - NAME REFERENCE	57

DIMENSIONS




MODEL	SIZE	A	B	C	D	E
1330	750mm 30in	1550mm 61in	1660mm 65½in	1180mm 46½in	1054mm 41½in	
1340	1000mm 40in	1800mm 71in	1920mm 75½in	1180mm 46½in	1054mm 41½in	
1430	750mm 30in	1550mm 61in	1660mm 65½in	1194mm 47in	1067mm 42in	
1440	1000mm 40in	1800mm 71in	1920mm 75½in	1194mm 47in	1067mm 42in	

VARIABLE SPEED CHANGE



MODEL	SIZE	A	B	C	D	E
1330V	750mm 30in	1550mm 61in	1660mm 65½in	1298mm 51in	1054mm 41½in	
1340V	1000mm 40in	1800mm 71in	1920mm 75½in	1298mm 51in	1054mm 41½in	
1430V	750mm 30in	1550mm 61in	1660mm 65½in	1298mm 51in	1067mm 42in	
1440V	1000mm 40in	1800mm 71in	1920mm 75½in	1298mm 51in	1067mm 42in	

VARIABLE SPEED CHANGE WITH "CE" STANDARD




MODEL	SIZE	A	B	C	D	E
1330V	750mm 30in	1550mm 61in	1660mm 65½in	1295mm 51in	1054mm 41½in	
1340V	1000mm 40in	1800mm 71in	1920mm 75½in	1295mm 51in	1054mm 41½in	
1430V	750mm 30in	1550mm 61in	1660mm 65½in	1295mm 51in	1067mm 42in	
1440V	1000mm 40in	1800mm 71in	1920mm 75½in	1295mm 51in	1067mm 42in	

SPECIFICATION AND ACCESSORIES


BRIEF SPECIFICATION				165mm 6mm/4TPI	
MODEL	1330 1330 V	1340 1340 V	1430 1430 V	1440 1440 V	
NOMINAL SIZE					
Swing over bed	330mm. 13"	330mm. 13"	356mm. 14"	356mm. 14"	
Swing over cross slide	195mm. 7 $\frac{7}{8}$ "	195mm. 7 $\frac{7}{8}$ "	220mm. 8 $\frac{5}{8}$ "	220mm. 8 $\frac{5}{8}$ "	
Height of center	165mm. 6 $\frac{1}{2}$ "	165mm. 6 $\frac{1}{2}$ "	178mm. 7"	178mm. 7"	
Distance between centers	750mm. 30"	1000mm.40"	750mm. 30"	1000mm.40"	
BED					
Width of bedways	206mm. 8 $\frac{1}{2}$ "	206mm. 8 $\frac{1}{2}$ "	206mm. 8 $\frac{1}{2}$ "	206mm. 8 $\frac{1}{2}$ "	
Total length of bed	1430mm.56"	1680mm.66"	1430mm.56"	1680mm.66"	
Gap type	Swing over gap	490mm. 19"	490mm. 19"	515mm. 20"	515mm. 20"
	Length of gap	240mm. 9 $\frac{7}{8}$ "	240mm. 9 $\frac{7}{8}$ "	240mm. 9 $\frac{7}{8}$ "	240mm. 9 $\frac{7}{8}$ "
	Width in front of face plate	146mm. 5 $\frac{3}{4}$ "	146mm. 5 $\frac{3}{4}$ "	146mm. 5 $\frac{3}{4}$ "	146mm. 5 $\frac{3}{4}$ "
SPINDLE					
Spindle nose mounting	D1-4 Camlock				
Spindle bore	38mm. 1-1/2"				
Taper of spindle bore	M.T. No.5				
Number of spindle speeds	8 (Standard)				
Range of spindle speeds	90-1800 R.P.M.				
Number of spindle speeds	16 (2 speeds Motor)				
Range of spindle speeds	45-1800 R.P.M.				
Number of spindle speeds	Variable speed change				
Range of spindle speeds	30-2200 R.P.M.				
TOOL SLIDE					
Total travel of cross slide	160mm. 6 $\frac{1}{4}$ "	160mm. 6 $\frac{1}{4}$ "	165mm. 6 $\frac{1}{2}$ "	165mm. 6 $\frac{1}{2}$ "	
Total travel of top slide	90mm. 3 $\frac{1}{2}$ "	90mm. 3 $\frac{1}{2}$ "	100mm. 4"	100mm. 4"	
Max. size cutting tool	16mm. 5/8"	16mm. 5/8"	22mm. 7/8"	22mm. 7/8"	
TAILSTOCK					
Total travel of barrel	120mm. 4-3/4"				
Taper in barrel	M.T. No.3				
Diameter of barrel	Dia. 45mm. 1-3/4"				
THREADS					
Leadscrew diameter & pitch	Dia. 25mm. pitch 6mm.		Dia. 1" 4T.P.I.		
Number of Inch threads	28 (Metric Leadscrew)		48 (Inch Leadscrew)		
Range of Inch threads	2 - 28 T.P.I.		1 - 56 T.P.I.		
Number of Metric pitches	37 (Metric Leadscrew)		26 (Inch Leadscrew)		
Range of Metric pitches	0.5 - 7.0 mm.		0.45 - 7.5 mm.		
FEEDS					
Feed rod diameter	Dia. 19mm.		Dia. 3/4"		
Number of feed change	42 (Metric system)		40 (Inch system)		
Range of longitudinal feeds	0.053 - 0.402mm./rev.		0.0011 - 0.0543in./rev.		
Range of cross feeds	0.026 - 0.201mm./rev.		0.0005 - 0.0271in./rev.		
MOTOR					
Main spindle motor	2.2 KW. 3 HP.				
Coolant pump motor	0.175 KW. 1/8 HP.				
Machine net weight	650 Kgs.	700 Kgs.	700 Kgs.	750 Kgs.	
We reserve the right to modify and improve our products.					

GENERAL LAYOUT OF LATHE



- | | |
|---|---|
| <p>1. Headstock</p> <p>2. Spindle</p> <p>3. Top slide</p> <p>4. Saddle & cross-slide</p> <p>5. Splash guard</p> <p>6. Tailstock</p> <p>7. Bed</p> <p>8. Mounting feet</p> <p>9. Tail-end plinth</p> | <p>10. Lead screw</p> <p>11. Chip pan</p> <p>12. Apron</p> <p>13. Foot brake</p> <p>14. Head-end plinth</p> <p>15. Mounting feet</p> <p>16. Gear box</p> <p>17. End cover</p> <p>18. Electrical box</p> |
|---|---|

FOUNDATION PLAN




MODEL: 1340F, 1440F, 1440V

LIFTING

Use the sling-chain to sling lathe showed as in fig 4 position the saddle and tailstock along the bed to obtain balance.

IMPORTANT: DO NOT USE SLINGS AROUND BED AS LEADSCREW AND FEEDSHAFT MAY BE BENT.



CLEANING

Before operating and controls, use white spirit or kerosene to remove the anticorrosion coating from all slideways and the endgear train.

DO NOT USE CELLULOSE SOLVENTS FOR CLEANING AS THEY WILL DAMAGE THE PAINT FINISH.


Machine surface becomes bright immediately after cleaning using machine oil or slideway lubricant. Use heavy oil or grease on the end gears.

INSTALLING

Located the machine on a solid foundation, allowing sufficient area all round for easy working and maintenance (see Foundation Plan). The lathe may be used free-standing or bolted to the foundation.

Free-standing: Position lathe on foundation and adjust each of the six mounting feet to take equal share of the load. Then using an engineers precision level on the bedways (as in Fig 5) adjust the feet to level up machine. Periodically check bed level to ensure continued lathe accuracy.


Fixed installation: Position lathe over six bolts (1/2 in. or 12 mm. diam.),set into the foundation to correspond with holes in the mounting feet. Accurately level the machine as in Fig 5, then tighten hold-down bolts and recheck bed level.



LUBRICATION CHECKS

Before operating the machine, make the following important checks:

1. The headstock is filled to level marked on oil sight window with Shell Tellus oil 27.
2. The gearbox is filled to level marked on oil sight window with Shell Tellus oil 27.
3. The carriage apron is filled to level marked on oil sight window with Shell Tonna 33.
4. In addition, apply light machine oil or way lubricant to the points shown on lubrication diagram which require daily oiling.



CHUCKS AND CHUCK MOUNTING


WARNING: GREY-IRON CHUCKS MUST NOT BE FITTED ON THIS HIGH-SPEED LATHE. USE ONLY DUCTILE IRON CHUCKS.

When fitting chucks or faceplate, first ensure that spindle and chuck tapers are scrupulously clean and that all cams lock in the correct positions. See Fig 7 ,it may be necessary when mounting a new chuck to re-set the camlock studs (A) to do this. Remove the cap-head locking screws (B) and set each stud so that the scribed ring (C) is flush with the rear face of the chuck-with the slit lining up with the locking screw hole (see Fig 7).


Now mount the chuck or faceplate on the spindle nose and tighten the three cams in turn. When fully tightened, the cam lock line on each cam should be between the two V on the spindle nose. If any of the cams do not tighten fully within these limit marks, remove the chuck or faceplate and re-adjust the stud as indicated in the illustration. Fit and tighten the locking screw (B) at each stud before remounting the chuck for work.

This will assist subsequent remounting. DO NOT INTERCHANGE CHUCKS OR FACE PLATES IF LATHE WITHOUT CHECKING UP CORRECT CAMLOCKING.


IMPORTANT: Take care note of speed limitations when using faceplate. 10 in. faceplates should not be run at speeds greater than 770 rev/min.



CORRECT




CORRECT



LATHE CONTROLS


1. Spindle speed digital readout. (for V-speed)
2. Spindle speed selector (HIGH or LOWER step).
3. Spindle speed adjusting knob. (for V-speed)
4. Gearbox, threads and feeds.
5. Apron, surfacing or sliding feeds.
6. Main motor rotation (forward and revers).
7. Footbrake.




ELECTRICAL CONTROLS

The power switches are fitted on the face of electrical in back of the headstock. Except the main switch, all electrical controls are fitted in the front of the headstock.

1. Move the power switch set at ON position then the indicator lamp glows.
2. Press the JOG button. The main drive motor can be running with a moment. (While the motor rotation lever is set in the neutral position).
3. Coolant pump ON/OFF select switch.
4. Press the RED button to stop the main motor and coolant pump.




- 1 - Indicator lamp
- 2 - Jog button
- 3 - Coolant pump switch
- 4 - Emergency stop switch



ELECTRICAL CONTROLS (Variable speed change)

The Main power switch are fitted on the front of Electrical box behind the Lathe (Head-end) All electrical controls are fitted to the front face of the Headstock and the top of Electricals box on the top of Headstock.

- (1),(2),POWER SWITCH BUTTON: when turn on the Main power switch (1) on the electrical cover; and (2) on the top of headstock, the pilot lamp (3) glows and the electricity is on.
- (3) PILOT LAMP: When power is on, the pilot lamp glows.
- (4) EMERGENCY STOP SWITCH: press the RED mushroom-head button to stop electric power, to stop the main motor and coolant pump.
- (5) INCHING: Press the GREEN button to move spindle slightly, it will make spindle speed selection very easy. (While the spindle rotation lever is set in the neutral position)
- (6) VARIABLE SPEED SELECTORS: adjusting spindle speed.
- (7) Spindle speed chart.
- (8) Coolant pump ON/OFF switchch.




SPEED CONTROLS (2 SPEED MOTOR)

Spindle speeds: Selected by the two lever controls and a electrical switch, on the headstock and stand. The sixteen available speeds are shown directly on the data plate. While the electrical switch set at (1) position, the small lever rotated right-hand side, it provides speeds from 1800–510 r.p.m., and rotated to left-hand side, it provides speeds from 330–90 r.p.m. Then move the large lever to the appropriately coloured arrow aligned with the required speed on the data plate. While the electrical switch set at (2) position, it provides speeds from 900–255 r.p.m. and 165–45 r.p.m.



When the small lever set at upper or bottom position, the spindle is free for hand rotation.

HIGH SPEED


LOW SPEED



ELECTRICAL SWITCH




1800rpm.




108rpm.


330rpm.




255rpm.



90rpm.




45rpm.



OPERATION

SPINDLE SPEED SELECTORS (Variable speed) HIGH SPEED (2200-165 RPM)




Main spindle can be variable controlled, from 2200 RPM to 30 RPM, divided into two groups, HIGH SPEED 2200-165 RPM, and LOWER SPEED 145-30 RPM.

Firstly, put the upper Handle (A) on the Headstock, to needed speed range.

(Note: DON'T CHANGE HANDLE'S POSITION WITH SPINDLE IN MOTION. SPINDLE MUST BE MOTIONLESS WHEN CHANGE HANDLE'S POSITION)

LOWER SPEED (405-30 RPM)



Then, adjust Variable Speed Selectors(B) to needed spindle speed.

Selectors(B) can change speed while spindle is rotating.

Spindle Speed Chart(C) equipped on the top of Headstock shows the RPM while spindle rotating.

THREADS AND FEEDS (Inch Gearbox)

All the threads and feeds directly available from the gear box are shown on the data plate fitted on the front of the gear -box. The setting of control levers is shown in Fig 13.

The B position of lever (Y) can provide a range of fine threads; the A position a coarse thread range. Do not select the range (A position) at spindle speeds higher than 770 rev/min.

THREADS AVAILABLE


40 Whitworth threads 4.0 to 112 t.p.i.

22 Metric threads 0.45 to 7.5 mm. pitch

The endgear train should be arranged as in the diagrams shown on the data plate to suit threading requirements.

Feeds: longitudinal feeds per spindle revolution range from .0012 to .0294 in. (0.0030 to 0.746 mm.)

Cross feeds per spindle revolution range from .0004 to .0108 in. (0.010 to 0.271 mm.)



T.P.I.		W/O	C1	C2	C3	D1	D2	D3	C4	D4	MM							
127	40	H	4	4½	5	5½	5¾	6	6½	7								
	40	G	.0294	.0261	.0235	.0214	.0205	.0196	.0181	.0168	C1	C3	D3	C3	C1	C2	C3	
127	25	H	8	9	10	11	11½	12	13	14	AH	7.5	6.0	5.0	4.8	4.5	4.0	
	50	G	.0147	.0131	.0117	.0107	.0102	.0098	.0090	.0084	BH	3.75	3.0	2.5	2.4	2.25	2.0	1.8
127	25	H	16	18	20	22	23	24	26	28	AF		1.5	1.25	1.2		1.0	0.9
	50	G	.0073	.0065	.0058	.0053	.0051	.0049	.0045	.0042	BF		0.75		0.6		0.5	0.45
127	25	F	32	36	40	44	46	48	52	56								
	50	E	.0042	.0038	.0034	.0031	.0030	.0028	.0026	.0024								
127	25	F	64	72	80	88	92	96	104	112								
	50	E	.0021	.0019	.0017	.0015	.0015	.0014	.0013	.0012								

THREADING DIAL INDICATOR

A. Whitworth threads

Located on right-hand side of the apron on lathes having an English leadscrew. Engage the indicator pinion with the leadscrew and tighten the handnut to retain indicator in engagement. To cut threads of an even number per inch, close the leadscrew nut as ANY line on the dial passes the datum mark. To cut threads of odd numbers per inch, close the leadscrew nut at any NUMBERED line.

Fractional threads of 1/2 or 1/4 t.p.i. may be cut by closing the nut at the SAME numbered line on each pass of the tool. This dial cannot be used with an English leadscrew to cut metric threads, or fractional threads. For these the leadscrew nut must be kept closed and the machine reversed by use of the Change-over switch, after each cutting pass and tool with drawal.

B. Metric threads

The thread dial used for cutting metric screw threads on lathes equipped with metric leadscrew. To provide for the various pitches of metric threads, several gears having different numbers of teeth are mounted on the lower end of the shaft. The vertical position of the thread dial indicator is changed as required so that the correct gear for the pitch of the thread to be cut will mesh with the leadscrew.



Each graduation on the dial is marked with a letter which indicates the points at which the halfnuts may be engaged for certain threads. A diagram is supplied with the thread dial to show which gear and which graduations must be used for each pitch of metric screw thread.

THREADING DIAL INDICATOR

SADDLE

APRON

LEADSCREW



WHITWORTH THREAD DIAL

TPI	↓	TPI	↓	TPI	↓
4	1-8	12	1-8	38	1-8
4 1/2	1-8	13	1-4	40	1-8
4 3/4	1	14	1-8	44	1-8
5	1-4	16	1-8	48	1-8
5 1/2	1-8	18	1-8	52	1-8
6	1-8	19	1-8	56	1-8
6 1/2	1-8	20	1-8	64	1-8
7	1-4	22	1-8	72	1-8
8	1-8	24	1-8	76	1-8
9	1-4	26	1-8	80	1-8
9 1/2	1-8	28	1-8	88	1-8
10	1-8	32	1-8	96	1-8
11	1-4	36	1-8	104	1-8

LEADSCREW PITCH 8T.P.I.


PC	T	↓	PC	T	↓
0.4	20	4	1.4	21	3
0.45	27	3	1.5	27	3
0.5	20	4	1.625	26	2
0.55	22	2	1.75	21	3
0.6	27	3	2.0	20	4
0.625	20	4	2.25	27	3
0.65	26	2	2.5	20	4
0.7	21	3	2.75	22	2
0.75	27	3	3.0	27	3
0.8	20	4	3.25	26	2
0.875	21	3	3.5	21	3
0.9	27	3	4.0	20	4
1.0	20	4	4.5	27	3
1.1	22	2	5.0	20	4
1.125	27	3	5.5	22	2
1.2	27	3	6.0	27	3
1.25	20	4	6.5	26	2
1.3	26	2	7.0	21	3
1.375	22	2			

LEADSCREW PITCH 4MM

APRON CONTROLS (Lever type)

In addition to handwheel traverse, the carriage can be power-operated through controls on the front of the apron, see Fig 16 knob (A). If move handle (A) upwards, carriage would do longitudinal-feed operation. If move handle (A) in middle position, it would do manual operation. If move handle (A) downwards, it would do cross-feed operation.


Lever (B) is pressed downward to engage the leadscrew nut for screwcutting. To avoid undue wear. Release the nut except when screwcutting.



CROSS-SLIDE AND TOP-SLIDE

A solid topslide is fitted as standard to the cross-slide. Carried on a rotatable base, the cross-slide is marked 90-0-90 deg. for accurate indexing. Handwheel dials are graduated in inch and metric divisions to suit the operating screw and fitted.

The cross-slide can be power operated, when the Lever (A) upwards or downwards. or it can be hand-operated using the large-diameter dial graduated in either inch or metric division to suit the operating screw and nut fitted.




TAIL STOCK

Can be free movement along the bed by unlocking the clamp lever (A).

The tailstock barrel is locked by lever (B).

The tailstock can be set-over for production of shallow tapers or for re-alignment. Release the clamping lever and adjust screws (S) at each side of the base to move tailstock laterally across the base. An indication of the setover is given by the datum mark (C) at the tailstock end face, as shown in Fig 18. Apply clamp lever after adjustment of set-over.




LATHE ALIGNMENT (Part.1)

With the lathe installed and running. We recommed a check on machine alignment before commencing work. Check levelling and machine alignment at regular periods to ensure continued lathe accuracy.

A. Headstock check

Take a light cut with a keen tool over a 6 in (150mm.) length of 2 in. dia. (50mm.) steel bar gripped in the chuck but not supported at the feed end. Micrometer readings at each end of the turbed length (at A and B) should be the same.

To correct a difference in readings, slacken the four headstock hold-down screws (S) and adjust the set-over pad (P) beneath the headstovk, to pivot the headstock about the dowel (D). Tighten all screws, after adjustment and repeat the test-cut / micrometer-reading, sequence until micrometer readings are indentical, so machine now cutting absolutely parallel.




LATHE ALIGNMENT (Part 2)

B. Tailstock check

Using a 12 in. (305mm.) ground steel bar fitted between headstock and tailstock centers, check the alignment by fitting a dial-test indicator to the topslide and traversing the center line of the bar.

To correct error release the tailstock clamp lever and adjust the two set-over screws provided continue with checking and correction until the alignment is perfect.




SERVICING AND MAINTENANCE

END GEAR TRAIN

Drive from headstock to gear-box is transmitted through a gear train enclosed by the headstock end-guard. Intermediate gears are carried on an adjustable swing frame (M).

Gears must be thoroughly cleaned before fitting and backlash maintained at .005in. (.127mm.) Lubricate gears regularly with thick oil or grease.

END GEAR TRAIN HEADSTOCK



DRIVING BELTS


To alter belt tension, remove the coverplate in back of the two screws (X) on the hinged motor platform. Ensure that the motor is correctly aligned with the lathe axis.

Light finger pressure at a point midway between motor and headstock pulleys should produce about 3/4 in. (19mm.) movement of each belt when under correct tension.

SLIDE WAYS ATTENTION

Tapered gib strips are fitted to slideways of saddle cross-slide and top (compound) slides so that any slackness which may develop can be rectified.


Ensure that slideways are thoroughly cleaned and lubricated before attempting adjustment. Then reset the gibs by slackening the rear gib screw and tightening the front screw. Check constantly for smooth action throughout full slide travel. Avoid over-adjustment which can result in increased wear-rate and stiff or jerky action.



GIB ADJUSTERS

CROSS-SLIDE NUT


This is adjustable for elimination of slackness which may develop in service. Reduce backlash by the cap-head screw in the rear of the nut. Then make only small adjustment by the cap-head screw. Before operating the cross-slide, check several times by hand to be sure of smooth operation throughout travel.



LUBRICATION (part 1)

The headstock and gearbox are splash-lubricated from an internal reservoir of oil (Shell Tellus 27). Check the oil level constantly to the mark on the oil sight window in the front end face of the headstock and gearbox. A weekly check is recommended. The oil need be changed every year. Oil through a filler cap in the top of the headstock and gearbox is covered by the end-guard. Drain from a drain plug in the bottom of the headstock and gearbox.

The apron is lubricated from an internal reservoir of oil. The oil sight window is in the front of the apron. A filler cap is in the top of the saddle. Refill the reservoir to the level of the oilsight with Shell Tonna oil 33. The apron can be drained by unscrewing a hexheaded drain plug in the bottom.



SERVICING AND MAINTENANCE


LUBRICATION (Part.2)

In addition, oil gun is provided to oil the oiler points on the saddle, cross-slide, cross-slide nut and top-slide with light machine oil or way lubricant, see Fig.

Oiler points, on the top of tailstock and on the bracket for leadscrew & feed road, must to be poured into oil every day by using oil gun.


It is recommended that all slideways, leadscrew and feed shaft are cleaned off (a bristle paint brush is useful for this) and lightly oiled after each period of work.

NOTE: Using incorrect grade of oil can cause damage.




SERVICING AND MAINTENANCE


Part to be lubricated	①	②	③	④
	HEADSTOCK	GEARBOX	APRON	SLIDE & TAILSTOCK
Recommendable lubricant	SHELL; TELLUS OIL 27	SHELL; TELLUS OIL 27	SHELL; TELLUS OIL 33	SHELL; TELLUS OIL 33 ~ 41
Filling method	OIL JUG	OIL JUG	OIL JUG	OIL GUN
Initial charge quantity	4.5 liter	1.5 liter	0.9 liter	
	3 Month	3 Month	1 Month	1 Day
Make up	Quantity	0.5 liter	0.2 liter	A little
	Interval	1 Year	1 Year	
Exchange	Quantity	4.5 liter	1.5 liter	0.9 liter
	Interval	1 Year	1 Year	




OPERATION

WIRING DIAGRAM (3 Phase 2-speed Motor)







al : Power switch 3 ϕ 3w 10A.

T : Control circuit Transformer 100VA.

M : Main Motor.

M1: Pump Motor.

A : Push button switch (jogging switch) type SB 3051A.

B : Flate type push button type SB 3091B.

C : Pilot light type. SP 301, 110V/15V, color: white.

D : Selecting switch. type ST 3021A.

el : Fuse base 600V, 30A, type SR-833.

e2 : Grass tube fuse 1A.

1c1: For main motor Reverse AC magnetic contactor coil AC 110V.
type C-11G3A1B.

1c2: For main motor Forward AC magnetic contactor coil AC 110V.
type C-11G3A1B.

2c1: For pump motor AC magnetic contactor coil AC 110V.
type C-11G3A1a.

1e1: Thermal overload relay for main motor. type RH-18M.

2e1: Thermal overload relay for pump motor. type RH-10E.

d : AC magntic contactor coil AC 110V. type C-11G3A1a.

Ls1: Limit switch End cover safety switch type 15G 22-B.

Ls2: Limit switch Brake precision. type 15GD-B.

Ls3: Limit switch Reverse precision. type 15GD-B.


Ls4: Limit switch Forward precision. type 15GD-B.

Cs1: 2 Speed Motor switch.

CIRCUIT DIAGRAM

P 1


FOR Variable Speed Change



CIRCUIT DIAGRAM

P 2





FOR Variable Speed Change




CIRCUIT DIAGRAM

P 3


FOR Variable Speed Change




HEADSTOCK




HEADSTOCK



HEADSTOCK for Variable speed change




HEADSTOCK




OPERATION

SPECIFICATION




OPERATION


SPECIFICATION




APRON Right hand, hever type



APRON Left hand, Lever type




APRON Left hand, Lever type




APRON

Left hand, Lever type




OPERATION

SPECIFICATION




SADDLE & CROSS-SLIDE




TOP SLIDE

TOOL POST




OPERATION


SPECIFICATION



BED & SHAFTS




CABINET & PANELS




SWING FRAME, END GEARS & COVER

Metric system




SWING FRAME, END GEAR & COVER




THREADING DIALS

INCH



MM



PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
2101	Main casting	1	2148	Cover	1
2102	Cover	1	2149	Gear 2M 42T	1
2104	Shaft	1	2150	Collar	1
2105	Cover	1	2151	Gear 2M 32T	1
2106	Pulley	1	2152	Collar	1
2107	Washer	1	2153	Gear 2M 32T	1
2108	Gear 2M 38T	1	2156	Shaft	1
2109	Gear 2M 23T	1	2157	Cover	1
2110	Collar	1	2158	Gear 2M 38T	1
2111	Gear 2M 30T	1	2159	Breaket	1
2112	Gear 2M 21T	2	2161	Rang selector	1
2113	Collar	3	2162	Rang selector	1
2114	Bore plug	1	2163	Collar	2
2117	Shaft	1	2164	Shaft	1
2118	Collar	1	2165	Pin	1
2119	Gear 2M 31T	1	2166	Lever	1
2120	Gear 2M 47T	1	2167	Gear 1.5M 35T	1
2121	Gear 2M 54T	1	2168	Gear 1.5M 45T	1
2122	Gear 2M 39T	1	2169	Shaft	2
2123	Collar	1	2170	Shift lever	1
2124	Collar	1	2171	Shift lever	1
2125	Gear 2M 21T	1	2172	Shift fork	2
2126	Gear 2M 60T	1	2173	Lever	4
2127	Bore plug	1	2174	Lever	3
2131	Spindle	1	2175	Handle	5
2132	Nut	1	2176	Coller	1
2133	Cover	1	2177	Handle	2
2134	Cover	1	2178	Shaft	1
2135	Collar	1	2179	Shift lever	1
2136	Gear 2M 82T	1	2180	Shift fork	1
2137	Gear 2M 43T	1	2181	Collar	1
2138	Gear 2M 38T	1	2182	Shift lever	1
2141	Shaft	1	2183	Shift fork	1
2142	Gear 2M 21T	1	2184	Coller	1
2143	Gear 2M 32T	1	2186	Stud	1
2144	Gear 2M 32T	1	2187	Stud	1
2147	Shaft	1	2188	Lever	1

PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
-----	-----	-----	-----	-----	-----
2201	Casting(INCH)	1	2239	Shaft	1
2202	Front cover	1	2240	Shaft	1
2204	Shaft	1	2241	Shaft	1
2205	Cover	3			
2206	Gear 1.75M 26T	1	2242	Fl. brg.	1
2207	Gear 2M 20T	1	2243	Gear 1.75M 36T	1
2208	Gear 2M 18T	1	2244	Gear 1.75M 21T	1
2209	Gear 2M 16T	1	2245	Nut	1
2210	Collar	1	2248	Handle	3
2211	Gear 2M 16T	1	2249	Gear 1.25M 20T	1
2214	Shaft	1	2250	Shaft	1
2215	Cover	1	2251	Gear 1.25M 28T	1
2216	Gear 1.75M 24T/2M 24T	1	2252	Lever	1
2219	Shaft	1	2253	Fork	1
2220	Gear 1.75M 28T	1	2255	Handle	3
2221	Gear 2M 24T	1	2256	Shaft	2
2223	Gear 2M 22T	1	2257	Lever	1
2224	Gear 2M 23T	1	2258	Lever	1
2226	Gear 2M 18T	1	2259	Fork	2
2227	Shear pin	1	2261	Casting(METRIC)	1
2228	Cover	1	2262	Front cover	1
2229	Nut	2	2263	Shaft	1
2230	Gear 1.75M 32T	1	2264	Shaft	1
2231	Cover	1	2265	Shaft	1
2232	Gear 1.75M 34T	1	2266	Shaft	1
2233	Collar	1	2269	Collar	1
2236	Shaft	1	2270	Collar	1
2237	Gear 1.75M 34T	1	2271	Washer	1
	Gear 1.75M 16T				
2238	Gear 2M 24T/2M 24T	1			

PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
-----	-----	-----	-----	-----	-----
2301	Casting	1	2327	Collar	1
2302	Handwheel	2	2330	Shaft	1
2303	Handle	2	2331	Handle	1
2304	Plug	4	2332	Handle	3
2305	Index ring	1	2333	Lever	1
2307	Shaft 2M 13T	1	2334	Breaket	1
2308	Keep assy.	1	2335	Half nut	1
2310	Rack pinion 2M 9T	1	2336	Gib	1
2311	Gear 2M 50T	1	2338	Worm	1
2312	Collar	4	2339	Cover	2
2313	Plug	1	2341	Casting	1
2315	Shaft	1	2342	Shaft	1
2316	Gear 2M 50T/20T	1	2343	Gear shaft	1
2318	Shaft	1	2344	Keep assy	2
2319	Gear 2M 22T	1	2345	Cam	1
2320	Coller	1	2346	Lever	1
2321	Gear 2M 22T	1	2347	Shaft	1
2322	Gear 2M 22T	1	2348	Collar	1
2325	Shaft	1	2349	Lever	1
2326	Gear 2M 22T	1	2350	Plug	1
			2351	Sliding plate	1

PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
2401	Saddle casting	1	2508	Keep assy.	1
2402	Cross-slide	1	2509	Handwheel	1
2404	Screw	1	2510	Index ring	1
2405	Nut	1	2512	Handle	1
2406	Collar	1	2513	Handle	1
2407	Gear 2M 14T	1	2514	Bolt	1
2408	Keep assy.	1	2515	Toolpost	1
2409	Handwheel	1	2516	Blot	1
2410	Index ring	1	2517	Nut	1
2412	Handle	1	2518	Nut	1
2413	Collar	1	2519	Gib	1
2414	Screw	1	2523	Screw	8
2415	Washer	1	2524	Washer	1
2416	Strip	2	2525	handle	1
2417	Strip	1	2527	Pad	1
2418	Gib	1	2529	Swiver Slide	1
2419	Gib	1	2530	Nut	2
2420	Gib screws	6	2531	Swiver Slide	1
2421	Nut	2	2532	Top slide	1
2422	Pirot	1	2533	Toolpost	1
2423	Wiper	2	2534	Nut	1
2424	Wiper	2	2601	Casting	1
2427	Handle	1	2602	Base	1
2428	Handle	1	2603	Gib	1
2429	Wiper	1	2604	Screw	1
2431	Screw	1	2605	Barrel	1
2432	Gear 2M 14T	1	2606	Nut	1
2433	Washer	1	2608	Keep	1
2434	Keep assy.	1	2610	Index ring	1
2435	Handwheel	1	2614	Pad	1
2436	Keep assy.	1	2615	Shaft	1
2437	Bearing cover	1	2618	Pirot block	1
2501	Swiver slide	1	2620	Shaft	1
2502	Top Slide	1	2621	Handle	1
2503	Pad	1	2622	Pins	2
2504	Screw	1	2623	Clamp plate	1
2505	Nut	1	2624	Screw	1
			2625	Nut	1

PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
2626	Keep	1	2733	Set-over pad	1
2701	Bed	1	2734	Screws	1
2702	Gap piece	1	2735	Swing Frame	1
2703	Bracket	1	2736	Swing Frame	1
2704	Leadscrew	1	2737	Washer	1
2705	Feed shaft	1	2738	Shaft	1
2706	Third-rod shaft	1	2739	Shaft collar	1
2707	Rack	1	2740	Washer	1
2708	Bracket	1	2741	Gear 1.25M 120T	1
2709	Sleeve	1		Gear 1.25M 127T	
2710	Fork	1	2742	Gear 1.25M 25T	1
2711	Handle	1	2743	Gear 1.25M 50T	2
2712	Collar	1	2744	Gear 1.25M 40T	1
2713	Collar	1	2745	Gear 1.25M 30T	1
2714	Pin	1	2746	Gear 1.25M 32T	1
2715	Box	1	2748	Washer	6
2716	Perspex cover	1	2749	Gear 1.25M 45T	2
2717	Box	1	2750	End Cover	1
2718	Guard	1	2751	Stud	2
2719	Shaft	1	2752	Nut	2
2720	Gear 1M 32T	1	2753	Stopper	1
2721	Washer	6	2754	Plug (Handstock)	1
2722	Collar	1	2755	Plug (Apron)	1
2723	Guard	1	2756	Gear 1.25M 24T	1
2724	Shaft	1	2757	Gear 1.25M 60T	1
2725	Gear 1.25M 20T	1	2758	Gear 1.25M 65T	1
2726	Gear 1.25M 21T	1	2759	Gear 1.25M 66T	1
2727	Gear 1.25M 22T	1	2760	Gear 1.25M 70T	1
2728	Gear 1.25M 26T	1	2761	Box	1
2729	Gear 1.25M 27T	1	2762	End cover	1
2730	Collar	1	2763	Bearing cover	1
2732	Dog	1	2764	Sliping clutch	1
			2765	Bush	1
			2766	Collar	1
			2767	Collar	1
			2768	Clutch	1
			2769	Collar	1

PARTS LIST

Part No.	Description	Quantity	Part No.	Description	Quantity
-----	-----	-----	-----	-----	-----
2801	Plinth (Stand)	1	2828	Bolt	2
2802	Plinth (Stand)	1	2829	Bolt	1
2803	Tray	1	2930	Cover	3
2804	Chip Tray	1	2901	Cam	3
2805	Front plate	1	2902	Pin	3
2806	Box	1	2903	Stud	3
2807	Plate	1	2904	Camlock wrench	1
2808	Tray	1	2915	Centor sleeve	1
2809	Cover	1			
2810	Cover	1			
2811	Cover	1			
2812	Pedal	1			
2813	Platform	1			
2814	Bracket	1			
2815	Guard	1			
2816	Pully	1			
2817	Shaft	1			
2819	Screw	1			
2820	Shaft	1			
2821	Shaft	1			
2822	Collar	1			
2823	Lever	1			
2824	Guard	1			
2825	Bar	1			
2826	Fulcrum	1			
2827	Fulcrum	1			

PARTS LIST

91121	Bearing No.6003	92312	Socket head cap screw	M8x12mm.
91122	Bearing No.6003Z	92316	" "	M8x16mm.
91123	Bearing No.6004	92320	" "	M8x20mm.
91125	Bearing No.6005	92330	" "	M8x30mm.
91131	Bearing No.6202	92335	" "	M8x35mm.
91133	Bearing No.6204	92340	" "	M8x40mm.
91135	Bearing No.6205	92345	" "	M8x45mm.
91532	Bearing No.30210	92350	" "	M8x50mm.
91543	Bearing No.32211	92370	" "	M8x70mm.
91544	Bearing No.32212			
91812	Thrust No.51101			
91813	Thrust No.51102			
91814	Thrust No.51103	92435	Socket head cap screw	M10x25mm.
91815	Thrust No.51104	92430	" "	M10x30mm.
91816	Thrust No.51105	92435	" "	M10x35mm.
91823	Thrust No.51202	92440	" "	M10x40mm.
91824	Thrust No.51203	92445	" "	M10x45mm.
91841	Thrust No.2901	92525	" "	M12x25mm.
91842	Thrust No.2902	92535	" "	M12x35mm.
91843	Thrust No.2903	92540	" "	M12x40mm.
91844	Thrust No.2904			
			92706	Set screw M6x6mm.
			92708	" " M6x8mm.
			92710	" " M6x10mm.
			92712	" " M6x12mm.
92116	Socket head cap screw	M5x16mm.	92716	" " M6x16mm.
92130	" "	M5x30mm.	92720	" " M6x20mm.
92145	" "	M5x45mm.	92725	" " M6x25mm.
			92808	Set screw M8x8mm.
			92814	Set screw M8x14mm.
			92012	Set screw M12x12mm.
92210	Socket head cap screw	M6x10mm.		
92212	" "	M6x12mm.		
92216	" "	M6x16mm.		
92220	" "	M6x20mm.		
92225	" "	M6x25mm.		
92230	" "	M6x30mm.		
92235	" "	M6x35mm.		
92240	" "	M6x40mm.		
92245	" "	M6x45mm.		
92250	" "	M6x50mm.		
92255	" "	M6x55mm.		

PARTS LIST

93112	Cap screw	1/41-1/4 in.	94625	Pin	5x25mm.
93314	Cap screw	3/8x1-1/2 in.	94630	"	5x30mm.
93320	" "	3/8x2 in.	94634	"	5x34mm.
93324	" "	3/8x2-1/2 in.	94635	"	5x35mm.
93330	" "	3/8x3 in.	94636	"	5x36mm.
93406	" "	1/2x3/4 in.	94640	"	5x40mm.
93412	" "	1/2x1-1/4 in.	94645	"	5x45mm.
93414	" "	1/2x1-1/2 in.	94650	"	5x50mm.
93416	" "	1/2x1-3/4 in.	94660	"	5x60mm.
93420	" "	1/2x2 in.			
93424	" "	1/2x2-1/2 in.	94830	Taper pin	4x30mm.
93430	" "	1/2x3 in.	94838	"	4x38mm.
93701	Nut	1/4 in.	95110	Key	4x10mm.
93703	Nut	3/8 in.	95115	"	4x15mm.
93704	Nut	1/2 in.	95120	"	4x20mm.
93806	Nut	6mm.	95140	"	4x40mm.
93903	Washer	3/8 in.	95210	Key	5x10mm.
93904	Washer	1/2 in.	95212	"	5x12mm.
93906	Washer	3/4 in.	95215	"	5x15mm.
			95220	"	5x20mm.
94102	Screw	1/8x1/4 in.	95225	"	5x25mm.
94103	Screw	1/8x3/8 in.	95230	"	5x30mm.
94202	Screw	3/16x1/4 in.	95235	"	5x35mm.
94203	"	3/16x3/8 in.	95240	"	5x40mm.
94303	"	1/4x3/8 in.	95244	"	5x44mm.
94308	"	5/32x3/16 in.	95245	"	5x45mm.
94403	Nail	2mm.	95250	"	5x50mm.
94409	Screw	1/4x1mm.	95260	"	5x60mm.
94508	Pin	3x8mm.	95270	"	5x70mm.
94512	"	3x12mm.			
94520	"	3x20mm.	95310	Key	6x10mm.
94524	"	3x24mm.	95315	"	6x15mm.
94612	Pin	5x12mm.	95325	"	6x25mm.
94616	"	5x16mm.	95397	"	6x110mm.
94620	"	5x20mm.	95398	"	6x115mm.

PARTS LIST








95375	Key	6x75mm.	96308	O-ring	8x12x2mm.
95390	"	6x90mm.	96311	"	11x16x2.5mm.
95420	Key	7x20mm.	96314	"	14x19x2.5mm.
95440	"	7x40mm.	96320	"	20x25x2.5mm.
95450	"	7x50mm.	96324	"	24x30x3.0mm.
95460	"	7x60mm.	96325	"	25x31x3.0mm.
95520	Key	8x20mm.	96334	"	34x40x3.0mm.
95530	"	8x30mm.	96338	"	38x45x3.5mm.
95540	"	8x40mm.	96343	"	43x51x4.0mm.
95550	"	8x50mm.	96344	"	44x50x3.0mm.
95560	"	8x60mm.	96358	"	58x64x3.0mm.
95570	"	8x70mm.	96519	Oil sight	3/4in (19mm.)
			96528	"	1-1/8in.(28mm.)
95712	Circlip	S-12mm.	96603	Plug	3/8 G.P.
95715	"	S-15mm.	96616	"	3/4 in. (P.V.C.)
95716	"	S-16mm.	96703	"	3/8 G.P.
95718	"	S-18mm.	96704	"	1/2 G.P.
95720	"	S-20mm.	96803	Elbow	3/8 G.P.
95725	"	S-25mm.	97115	Spring	3/16in. x 15mm.
95730	"	S-30mm.	97208	Spring	1/4in.x8mm.
95738	"	S-38mm.	97210	"	1/4in.x10mm.
95740	"	S-40mm.	97220	"	1/4in.x20mm.
95750	"	S-50mm.	97225	"	1/4in.x25mm.
95755	"	S-55mm.	97230	"	1/4in.x30mm.
95835	Circlip	R-35mm.	97235	"	1/4in.x35mm.
95847	"	R-47mm.	97250	"	1/4in.x50mm.
95906	Circlip	E-6mm.	97420	Spring	3/8in.x20mm.
95912	"	E-12mm.	97430	"	3/8in.x30mm.
95915	"	E-15mm.	97435	"	3/8in.x35mm.
95919	"	E-19mm.	97440	"	3/8in.x40mm.
			97460	"	3/8in.x60mm.
96103	Oil seal TC	25x45x11mm.			
96104	Oil seal TC	25x40x8mm.			






PARTS LIST

97611	Spring	99211	Gasket
97621	"	99212	"
		99213	"
		99214	"
97801	Ball steel 1/4in. dia.	99215	"
97803	" " 3/8in. dia.	99216	"
		99217	"
		99221	"
97902	Oil 5/16in.	99222	"
		99223	"
98175	Belts Vee A-75in.	99224	"
		99225	"
98713	Headle 3/8 in. (Black)		
98902	Brake shose assy.		

STATIC ACCURACY TEST

CNS

TYPE:		MACHINE SERIAL NO.		
NO.	SUBJECT OF MEASUREMENT	ILLUSTRATION	PERMISSIBLE ERROR	MEASURED ERROR
1.	Levelling of machine	(a) in longitudinal direction	 (convex)	± 0.04 mm/m
		(b) in transverse direction		± 0.04 mm/m
2.	Taper of spindle runs true	 300 mm long A B	Position A : 0.01 mm	
			Position B : 0.02 mm	
3.	Spindle parallel with traverse of carriage	(a) in vertical plane	 a b	(a) 0.02/ 300 mm
		(b) in horizontal plane		(b) 0.02/ 300 mm
4.	Upper Slide (Parallelism of the Slide Longitudinal Movement to the Spindle Axis)		0.01/150 mm	
5.	Axis of centres parallel with bed in vertical plane	 A B	0.02/ 300 mm	

6.	Tailstock spindle parallel with carriage guides (carriage traverse)	(a) in vertical plane		(a) 0.02/ 150 mm	
		(b) in horizontal plane		(b) 0.01/ 150 mm	
7.	Centring register of spindle runs true		0.01 mm		
8.	Spindle for axial float and true running of face of spindle flange		0.015 mm		
9.	Centre runs true		0.015 mm		
10.	Working accuracy of lathe on cylindrical turning		0.015mm (cylindricity) (D=25mm ~50mm)		
CHIEF ENGINEER :			INSPECTING ENGINEER :		